

Valita®Titer Plus Materials Safety Statement

ValitaCell Ltd,
NIBRT,
Dublin,
A94X099
Ireland
P: +353 1 215 8130
E: support@valitacell.com



Version 1. 2020

All working solutions for the intermediate Valita®Titer Plus plate product (Cat. No. VAL004), are not classified as hazardous materials by the current state of scientific knowledge.

For Valita®Titer Plus plate, fluorescently labelled protein solutions are dispensed and dried-down. Consequently, the Valita®Titer Plus plate is not classified as hazardous materials and an MSDS is not required [as per guidelines].

Valita®Titer Plus plates are chemically synthesized and do not contain animal or cell culture derived products and the material was not derived from any animal or cell culture derived products.